


BOP SGT-02

Frame 6B COGEN
IGV LVDT Misalignment/Wear


BOP Frame 6B IGV LVDT Wear




BOP Frame 6B IGV LVDT Wear



BOP Frame 6B IGV LVDT Wear




BOP Frame 6B IGV LVDT Wear



Clearance
issue on
(old)
actuator
guide

BOP Frame 6B IGV LVDT Wear



Tighter clearance on (new)
actuator guide